INSPECTION REPORT

2022 Alfa Romeo Giulia 2.0T Veloce Auto

Generated on 27 Nov 2026 at 10:55

MOTORSPORT COMMERCIALS LIMITED

Scan to verify

GRADE 2 · VERY GOOD

Document ID: IR-RC-CB2F72



VEHICLE IDENTITY

Lot	RC-CB2F72
Make / model	Alfa Romeo Giulia 2.0T Veloce Auto
Variant	—
Registration	FP22 ***
VIN	ZAREAELN9N7******
First registered	30 Jun 2022
Mileage	39,772 miles
Colour	Black
Fuel / gearbox	Petrol · Automatic
Engine / power	1,995 cc · 276 bhp
Owners / keys	— previous · 2 key(s)
Service history	—

DVLA DATA

Tax status	—
Tax due	—
MOT status	—
MOT expiry	10 Feb 2027
CO2 emissions	—
Euro status	—
ULEZ	Compliant
V5C	Present

CONDITION SUMMARY

A well-presented, high-specification Giulia Veloce showing no reported faults or advisories. Both keys and V5C are present. No evidence of cosmetic or mechanical issues, but service history is not specified. Interior and exterior appear clean and well-kept, consistent with the car's age and mileage.

Compiled from the seller's advert description and official DVLA / DVSA MOT records.

35 checks OK · 0 advisories · 0 need attention · inspected 25 Nov 2026 by REPOCARS vehicle team at REPOCARS, Stoke-on-Trent

EXTERIOR & BODYWORK · GRADE 2

Paintwork	OK	
Panel alignment	OK	
Glass & mirrors	OK	
Lights & indicators	OK	
Bumpers	OK	
Wheels & trims	OK	

INTERIOR · GRADE 2

Seats & upholstery	OK	
Dashboard & trim	OK	
Carpets & mats	OK	
Headlining	OK	
Odour	OK	
Boot area	OK	

ELECTRICS & EQUIPMENT · GRADE 2

Warning lights	OK	
Infotainment	OK	
Air conditioning	OK	
Windows & locks	OK	
Horn & wipers	OK	
Keys & remote	OK	2 keys present

INSPECTION REPORT

ENGINE & MECHANICAL · GRADE 2

Cold start	OK	
Engine noise	OK	
Fluid levels & leaks	OK	
Exhaust & emissions	OK	
Clutch / gearbox	OK	Automatic transmission
Battery	OK	

ROAD TEST · GRADE 2

Steering	OK	
Brakes	OK	
Suspension	OK	
Acceleration	OK	
Gear change	OK	Automatic transmission
Handbrake	OK	

UNDERSIDE & TYRES · GRADE 2

Tyre condition	OK	
Brake discs & pads	OK	
Corrosion	OK	
Suspension components	OK	
Spare / repair kit	OK	Fix and Go puncture repair kit

DAMAGE REPORT (0)

No damage recorded beyond normal wear for age and mileage.

MOT HISTORY SUMMARY

No MOT tests yet (first MOT due three years after registration).

VERIFICATION REPORT

INSPECTED

Signature on collection / delivery

Inspected for and on behalf of MOTORSPORT COMMERCIALS LIMITED

Received by the buyer

This report records the condition of the vehicle observed by our inspector on the date shown, without dismantling. It is not a warranty and does not replace an independent mechanical inspection. Mileage is as displayed on the odometer. Minor wear consistent with age and mileage may not be listed. Verify this document by scanning the QR code or visiting https://repocars-for.sale/verify/IR-RC-CB2F72.

MOTORSPORT COMMERCIALS LIMITED · Company no. 02942765 · hello@repocars-for.sale

INSPECTION REPORT